

कायालय
अनुविभागीय अधिकारी
लोक निर्माण विभाग, पश्चिम उपसंभाग
भोपाल म0प्र0

क्रमांक 235 / सहा अनु.अधि / 2019

भोपाल, दिनांक 20/02/2019

To,
The Manager
Sagar Public School
Village Sikandrabad, Ratibad
District Bhopal.

Reference- Your letter No. Nil Dated 12/02/2019.


Subject- Checking of the Structural Integrity of the School Building.

Sir,

With reference to the aforesaid please note that the design documents and drawings of the construction of your school building at Sagar Public School, Village Sikandrabad, Ratibad District Bhopal have been reviewed and the rapid visual survey of the said building was conducted on 18/02/2019.

Based on the review of the documents and the Visual Survey of the building it can be certified the design and the construction of the building is as per the prevailing codes of practice and the building is well designed to sustain the gravity loads as per the Indian Standard codes of Practice.

The visual observations we do not take the responsibility of any changes / errors during construction.


अनुविभागीय अधिकारी
लोक निर्माण विभाग, पश्चिम उपसंभाग, भोपाल
P.W.D. West Sub-Division, Bhopal

